Wednesday, 6/6/2007 1:57:28 PM Kim Johnston User: **Process Sheet** : FLOAT SKIDTUBE **Drawing Name** Customer : CU-DAR001 Dart Helicopters Services Job Number : 32795 : 10366 Estimate Number : D412742013 Part Number P.O. Number UNDER REVIEW PI **Drawing Number** Ţhis Issue : 6/6/2007 : N/A Project Number Prsht Rev. : LANDING GEAR **Drawing Revision** : N/A First Issue : MA : 32794 Material Previous Run : 6/30/2007 Each 1 Um: Due Date Written By Checked & Approved By : Est Rev: A 05.10.13 New Issue KJ/JLM Comment As per DSI9336 JLM Est Rev:B 06-06-08 Additional Product Job Number: Machine Or Operation: Description: Seq. #: DOCUMENT CONTROL 1.0 3 02.08.11 Comment: DOCUMENT CONTROL CHG 003 P\$ 07.06-11 Photocopy bluefile and create labels per PPP D412-742-013 GH0001 FLOAT SKID ASSEMBLY 2.0 Comment: Sub-Component FLOAT SKID ASSEMBLY D412-742-043 B 32794A 3.0 D2571 Comment: Qty.: 1.0000 Each(s)/Unit 1.0000 Each(s) Total: Pick: Description Qty Part Number Saddle Fwd Outside 1 D2571 4.0 D2572 Saddle, Fwd, In in. Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: Description Qty Part Number 1 D2572 Saddle Fwd Inside D2573 5.0 Comment: Qty.: 1.0000 Each(s)/Unit 1.0000 Each(s) Total: Qty Part Number Description 1 D2573 Saddle Aft Outside

Page 1

Form: infocess

| Dart Aerospace Lt |
|-------------------|
|-------------------|

| W/O: | | WORK ORDER CHANGE | S | | | | |
|------|------|-------------------|----|------|-----|-------------------------------------|--------------------------|
| DATE | STEP | PROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | : | | | | |
| | | • | | | | | |
| | | · | | | _ | . 1 | |
| , | | | | | | | |
| | | | | | | | <u> </u> |

| Part No: _ | PAR #: | Fault Category: | NCR: Yes | No | DQA: | Date: |
|------------|------------|-----------------|----------|-------|--------|-------|
| | | | QA: N | 1/C C | losed: | Date: |

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | | | |
|------|------|----------------------------------|---|------------------------------|----------------|--------------|-----------------------|--------------------------|--|--|--|
| | | Description of NC | Description of NC Corrective Action Section B | | | Verification | Annroval | Approval | | | |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Approval Chief Eng | Approval QC Inspector | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| 1 | | | | | | | | | | | |
| | | | | | | | - | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

Wednesday, 6/6/2007 1:57:28 PM Date: User: Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: FLOAT SKIDTUBE Part Number: D412742013 Job Number: 32795 Job Number: Description: Seq. #: Machine Or Operation: Saddle, Aft, In D2574 6.0 Comment: Qty.: Total: 1.0000 Each(s) 1.0000 Each(s)/Unit Pick: **Qty Part Number** Description Batch Saddle Aft Outside 1 D2574 D2747 7.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Qty Part Number Description Batch 4 D2747 Bolt D2876 Saddle Spacer 8.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description 2 D2876% Saddle Spacer D2877 9.0 Saddle Spacer Comment: Qty.: 2.0000 Each(s)/Unit 2.0000 Each(s) Total: Pick: **Qty Part Number** Description Batch Saddle Spacer D2877 10.0 D34031 Bushing Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: Qty Part Number Description Batch 16 D3403-1 Bushing 11.0 D34033 Bushing Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: Qty Part Number Description Batch 8 D3403-3 Bushing

| Dart Aerospac | :e | Ltd |
|---------------|----|-----|
|---------------|----|-----|

| W/O: | | | Α, | ORK ORDER CH | ANGES | | | | |
|----------|--------------|------------------------------------|----------------------|--|-----------|----------------|------------------------|----------------------------------|---|
| DATE | STEP | . ¿ PRO | OCEDURE CH | IANGE | | Ву | Date Q | ty Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | | | |
| | | | | · · · | | | | | |
| | | | | | | | | | |
| | | | | | | | | · | |
| Part No: | · | PAR #: | Fault Ca | tegory: | NCI | R: Yes N | lo DQA:_ | Date: _ | |
| | | • | | | | QA: N/ | C Closed: _ | Date: _ | |
| NCR: | | | WORK OR | DER NON-CONFO | RMANCE | (NCR) | | | |
| DATE | STEP | Description of NC Section A | Initial Chief Eng | Corrective Action Action Descrip Chief Eng | Section B | Sign & Date | Verification Section C | | Approval QC Inspector |
| | | | | g | | | | | |
| | | | | | | | | | 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| | | | | * | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| NOTE: Da | ate & initia | al all entries | | | | | | | |

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevD

Wednesday, 6/6/2007 1:57:28 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 32795 Job Number: Description: Seq. #: Machine Or Operation: Lug Assembly D3405041 12.0 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: Description **Qty Part Number** GHW Lug 1 D3405-041 D3405043 13.0 Comment: Qty.; 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: Qty Part Number Description 1 D3405-043 GHW Lug 14.0 AN4C6A Comment: Qty.: 16.0000 Each(s) 16.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Bolt 16 AN4C6A 15.0 AN4C46A Comment: Qty.: 4.0000 Each(s) 4.0000 Each(s)/Unit Total: Description **Qty Part Number** 4 AN4C46A 16.0 AN4C52A 8.0000 Each(s) Comment: Qty.: 8.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Batch 8 AN4C52A Bolt AN6C12A BOLT 17.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description Batch 14289 Bolt 8 AN6C12A

| W/O: | | | WORK ORDER | CHANGES | | | | |
|---------|------|--------|-----------------|----------|-----------|-----|-------------------------------------|--------------------------|
| DATE | STEP | PR | OCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| f | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Part No | • | PAR #: | Fault Category: | NCR: Yes | No DQ | A: | Date: | |
| | | | | QA: | N/C Close | d: | _ Date: _ | |

| NCR: | | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | | |
|------|------|-------------------|----------------------------------|------------------------------|----------------|---------------------------|-----------|--------------------------|--|--|--|
| | | Description of NC | | Corrective Action Section B | | | Approval | T . | | | |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Verification Section C | Chief Eng | Approval QC Inspector | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

Wednesday, 6/6/2007 1:57:28 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 32795 Job Number: Description: Seq. #: Machine Or Operation: WASHER AN960C416L 18.0 Comment: Qty.: 32.0000 Each(s)/Unit Total: 32.0000 Each(s) Pick: Description M10454 Qty Part Number Batch 32 AN960C416L Washer__ WASHER AN960C616L 19.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: Qty Part Number Description 8822 i 8 AN960C616L Washer WASHER AN960C716L 20.0 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Comment: Qty.: Pick: Description **Qty Part Number** Washer 16 AN960C716L 21.0 MS210434 Nut 29.0000 Each(s)/Unit Total: Comment: Qty.: 29.0000 Each(s) Pick: **Qty Part Number** Description 29 MS21043-4Nut <u>M/DU.537</u> 101390 (114) ZM 103415(114) 22.0 NAS1515H4L Inventory Comment: Qty.: 32.0000 Each(s)/Unit Total: 32.0000 Each(s) Pick: **Qty Part Number** Description Washer 32 NAS1515H4L

| Dart Aerospace I |
|------------------|
|------------------|

| W/O: | | WORK ORDER CHANGES | | | | | |
|---------|------|---------------------------|--------|------------|------------|-------------------------------------|--------------------------|
| DATE | STEP | PROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | |
| | : | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | <u> </u> | | |
| Part No | • | PAR #: Fault Category: No | CR: Ye | No DQ | A : | Date: _ | |
| | | | QA: | N/C Closed | d: | Date: _ | |

| NCR: | | , | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | | | |
|------------|------|-------------------|----------------------------------|------------------------------|----------------|------------------------|-----------|--------------------------|--|--|--|--|
| | | Description of NC | | Corrective Action Section B | | | Approval | Approval | | | | |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Verification Section C | Chief Eng | Approval QC Inspector | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| . <u>-</u> | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| ı | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Date: Wednesday, 6/6/2007 1:57:28 PM User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 32795 Part Number: D412742013 Job Number: Description: Seq. #: **Machine Or Operation:** 23.0 NAS1515H6L Inventory 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Comment: Qtv.: Pick: Description Qtv Part Number Washer 8 NAS1515H6L NAS1515H7L 24.0 Inventory Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: Description Qty Part Number Washer 16 NAS1515H7L Tow Ring 25.0 D3407041 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Batch D3407-041 **TOW RING** D34173 26.0 2.0000 Each(s) Comment: Qty.: 2.0000 Each(s)/Unit Total: Pick: Description Qty Part Number WASHER 2 D3417-3 27.0 D34561 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description Batch **WASHER** D3456-1 28.0 AN4C7A Comment: Qty.: 4.0000 Each(s) 4.0000 Each(s)/Unit Total; Bolt Batch:

| NCR: | | , | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | | | |
|------|------|-------------------|----------------------------------|------------------------------|----------------|--------------|-----------------------|-------------------------|--|--|--|--|
| | | Description of NC | | Corrective Action Section B | | Verification | Annessal | | | | | |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Approval Chief Eng | Approval QC Inspecto | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | : | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | ; | | | | |

Wednesday, 6/6/2007 1:57:28 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 32795 Part Number: D412742013 Job Number: Description: Seq. #: Machine Or Operation: INSPECT 100% KITS FOR COMPLETENESS 29.0 QC4 Comment: INSPECT 100% KITS FOR COMPLETENESS PACKAGING RESOURCE #1 30.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-013 Location: 31.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE U 2-07-12 Job Completion

| Dart | Aero | space | Ltd |
|------|------|-------|-----|
|------|------|-------|-----|

| W/O: | | WORK ORDER CHANG | SES | | | | |
|---------|------|------------------------|----------|---------------------------------------|-----|-------------------------------------|-------------------------|
| DATE | STEP | PROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approva QC Inspector |
| | | | | | | | |
| | | | | | | | |
| | | | | · · · · · · · · · · · · · · · · · · · | | | |
| | | | | | | | |
| Part No | | PAR #: Fault Category: | NCR: Yes | No DQ | A: | Date: _ | |
| | | | QA: | N/C Close | d: | Date: _ | |

| | , | WORK ORDE | ER NON-CONFORMAN | CE (NCR) | | | |
|------|-------------------|------------------------|--|---|--|--|---|
| | Description of NC | | Corrective Action Section E | 3 | Verification | Approval | Approval QC Inspector |
| STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Chief Eng | |
| | | | | | | | |
| | ť | | | | | i | |
| | | | | | | | |
| | | | | | | | |
| | | · | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | STEP | STED Description of NC | STEP Description of NC Section A Initial | STEP Description of NC Section A Initial Action Description | STEP Description of NC Section A Initial Action Description Sign & | STEP Section A Initial Action Description Sign & Section C | STEP Description of NC Section A Section B Initial Action Description Sign & Verification Section C Chief Eng |

Dart Aerospace Ltd. Wednesday, 6/6/2007 1:57:58 PM Date: Kim Johnston User: **Process Sheet** : FLOAT SKID ASSEMBLY **Drawing Name** Customer : CU-DAR001 Dart Helicopters Services Job Number : 32795A **Estimate Number** : 10756 Part Number : D412742043 P.O. Number : NA . D3391 REV F **Drawing Number** This Issue 6/6/2007 S.O. No. : : N/A Project Number Prsht Rev. MA : LANDING GEAR NA **Drawing Revision** First Issue : 32794A Material Previous Run : 6/30/2007 Qty: 1 Um: **Due Date** Written By Checked & Approved By KJ/JLM : Est Rev A 05.10.13 New Issue Comment ECN 773 dwg @ rev.D EC Est Rev B 06.02.13 Est Rev:C 07-05-28 JLM As per Rev F Additional Product Job Number: Description: **Machine Or Operation:** Seq. #: DOCUMENT CONTROL 1.0 Comment: DOCUMENT CONTROL If D412-742-043 is a W/O on it's own, Photocopy bluefile and create labels per PPP D412-742-043 D3391023 2.0 Mid Tube Assembly Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) pick: Part Number Description Qty D3391-023 Mid Tube Assembly 1 3.0 D3391025

1.0000 Each(s)/Unit Comment: Qty.: 1.0000 Each(s) pick: Qty Part Number Description D3391-025 Aft Tube Assembly


1.0000 Each(s)/Unit

Total:

Total:

D35641 4.0

WEARSHOE



Comment: Qty.: WEARSHOE Batch:



Each

| Dart Ae | rospace | e Ltd | | | | | | | |
|---------|---------|-------------------|----------------------|------------------------------|----------------|--------------|--------|-------------------------------------|--------------------------|
| W/O: | | | W | ORK ORDER CHANGES | | | | | |
| DATE | STEP | PRO | CEDURE CHA | ANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Part No | | PAR #: | Fault Cate | egory: No | CR: Yes | No DQ | A: | Date: | |
| | | | | | QA: N | C Close | d: | _ Date: _ | |
| NCR: | | V | VORK ORD | ER NON-CONFORMANC | E (NCR |) | | | |
| | | Description of NC | | Corrective Action Section B | | Verific | cation | Approval | Approval |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Secti | | Chief Eng | QC Inspector |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | · | 1 | | 1 | | | ! | |

Wednesday, 6/6/2007 1:57:58 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 32795A Job Number: Description: Seq. #: Machine Or Operation: D35643 WEARSHOE 5.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) WEARSHOEK 3/4/9 WEARSHOE 6.0 D35645 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) WEARSHOE GASKET D35661 7.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) **GASKET** Batch: **GASKET** 8.0 D35665 Comment: Qty.: Total : 1.0000 Each(s)/Unit 1.0000 Each(s) **GASKET** 31421 Batch: BOLT 9.0 AN3C4A Comment: Qty.: 24.0000 Each(s)/Unit Total: 24.0000 Each(s) **BOLT** Batch: BOLT 10.0 AN3C6A Comment: Qty.: 12.0000 Each(s)/Unit Total: 12.0000 Each(s) **BOLT** Batch: BOLT 11.0 AN3C7A 8.0000 Each(s)/Unit Total: Comment: Qty.: 8.0000 Each(s) **BOLT** m103668 Batch:

Form: mrocess

Page 2

| Dart Ae | rospace | e Ltd 🦠 | | | | | | | |
|---------|---------|----------------------------------|----------------------|----------------------------|-----------|------------|--------------|-------------------------------------|------------|
| W/O: | | • | WC | ORK ORDER CHA | NGES | | | | |
| DATE | STEP | PRO | OCEDURE CHA | NGE | Ву | | Date Qty | Approval Chief Eng / Prod Mgr | Approve |
| | | 30.0 | | ή, | | | | | |
| | | • | | | | | | | |
| Part No |): | PAR #: | Fault Cate | gory: | NCR: Ye | es N | o DQA: | Date: | |
| | | | | | | | Closed: | _ Date: _ | |
| NCR: | | \ | WORK ORDI | ER NON-CONFOR | RMANCE (N | CR) | | | |
| DATE | CTED | Description of NC | | | Section B | | Verification | Approval | Approva |
| DATE | SIEP | STEP Description of NC Section A | Initial Chief Eng | Action Descripti Chief Eng | on Sig | n & ate | Section C | Chief Eng | QC Inspect |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | , | | |
| | | , | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | : | |

Date: Wednesday, 6/6/2007 1:57:58 PM User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 32795A Job Number: Description: Seq. #: Machine Or Operation: AN960C10L washer 12.0 Comment: Qty.: Total: 44.0000 Each(s) 13.0 Comment: HAND FINISHING RESOURCE #1 1-Spray inside tube of D3391-021/-023/-025 with LPS-3 as per Dwg D3391 A/R LPS-3 M164161 2-Install tubes together and seal them all the way around using Sikaflex 241/291. Ensure tube ends line-up with saddle holes for proper alignment. using 7/16" "T" Pins. Sikaflex-241/-291 <u>M10473</u>2 01.50 Expiry date: 3-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped with the SS washer. Coat bolts with LPS "procyon". Seal all bolts with sikaflex exept ones with inserts on inside of tube ,hand tighten only bolts with no sikaflex. LPS Procyon MIOUZS **A/R** Expiry date: 4-Remove "T" pins once sikaflex is dry. 5-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser. INSPECT WORK TO CURRENT STE 14.0 QC5 WORK TO CURRENT STEP PACKAGING RESOURC 15.0 PACKAGING Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-043 Location:_ PPP 32878 /o PPP Rev:

Dart Aerospace Ltd W/O: WORK ORDER CHANGES DATE STEP PROCEDURE CHANGE By Date Qty Prod Mgr QC Inspector Part No: PAR #: Fault Category: NCR: Yes No DQA: Date: CHANGE

QA: N/C Closed: ____ Date: ____

| NCR: | | | WORK ORD | DER NON-CONFORMANC | E (NCR) | | | |
|------|------|-------------------|----------------------|------------------------------|----------------|--------------|-----------------------|--------------------------|
| | | Description of NC | | Corrective Action Section B | | Verification | Annroyal | Ammayal |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Approval Chief Eng | Approval QC Inspector |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | <u> </u> | | |
| | | | | | ٠ | , | | |
| | | | | | | . - | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

Date:

Wednesday, 6/6/2007 1:57:58 PM

User:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKID ASSEMBLY

Job Number: 32795A

Part Number: D412742043

Job Number:



Seq. #:

Job Completion

Machine Or Operation:

Description:

16.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE



U A. A. 12

| W/O: | | WORK ORDER CHANGES | | | | | |
|---------|------|---------------------------|--------|-------------|------------|-------------------------------------|------------------------|
| DATE | STEP | PROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approva QC Inspecto |
| | | | | | | | |
| | | | | | | | |
| | - | | | | | | |
| | | | | | | | |
| Part No | : | PAR #: Fault Category: NO | R: Yes | s No DQA | \ : | Date: _ | |
| | | | O 4 - | NI/C Classe | 1. | Data | |

| NCR: | | | WORK ORD | ER NON-CONFORMAN | CE (NCR) | | | |
|------|------|-------------------|----------------------|------------------------------|----------------|--------------|-----------|--------------|
| | | Description of NC | | Corrective Action Section E | 3 | Verification | Approval | Approval |
| DATE | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Chief Eng | QC Inspector |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | * | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

